



Attorney Docket No. 1664.1001

cafc

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Tetsuo MURAJI, et al.

Application No.: 10/084,945

ATTENTION

Confirmation No.: 8275

CERTIFICATE OF CORRECTION

Filed: March 1, 2002

BRANCH

U.S. Patent No.: 6,867,582

Batch No.:

Issued: March 15, 2005

For: NON-CONTACT POSITION SENSOR

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Certificate
AUG 05 2005
of Correction

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date:

August 2, 2005

By:

Paul I. Kravetz

Paul I. Kravetz
Registration No. 35,230

1201 New York Ave, N.W., Suite 700
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

AUG 5 - 2005

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,867,582

DATED : March 15, 2005

INVENTOR(S) : Tetsuo MURAJI, et al.

Col. 22, line 45, after "wherein" insert --the--.

Col. 23, line 38, change "M θ " to --M θ a1--.

Col. 24, line 31, delete "each".

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP
1201 New York Ave., N.W.
Suite 700
Washington, DC 20005

PATENT NO. 6,867,582

No. of add'l copies
@ 50¢ per page

⇒

AUG 5 - 2005